

PON'T ORDER A WHOLE NEW ANTENNA MAST GROUP FLUID FILTER ASSEMBLY WHEN THE FILTER'S INDICATOR CHANGES COLOR.

THE WHOLE ASSEMBLY, NSN 4330-01-182-7885. COSTS MORE THAN \$90. INSTEAD, REPLACE JUST THE FILTER ELEMENT, NSN 4330-01-413-5257, FOR ABOUT \$13.



TO CLEAN THE RADAR'S HIGH POWER CABLE. USE ISOPROPYL ALCOHOL WIPES MADE BY CRAWFORD TOOL, GET 100 WIPES FOR LESS THAN \$14 BY CALLING CRAWFORD AT (800) 272-9373 OR ORDERING THEM OVER THE INTERNET www.crawfordtool.com/techspray.html



ELECTRICAL POWER PLANT (EPP) III WITH NSN 9390-12-348-2726. THE MATTING'S UNIT OF ISSUE IS BEING CHANGED FROM INCHES TO METER. IT TAKES 4.5 METERS OF MATTING TO COVER ONE ENTIRE GENERATOR SET. 1101

ORDER RUBBER MATTING FOR THE